

Notice of References Cited	Application/Control No. 10/708,341		Applicant(s)/Patent Under Reexamination TAKEDA ET AL.	
	Examiner CUONG H. NGUYEN		Art Unit 3661	Page 1 of 1

U.S. PATENT DOCUMENTS

*		Document Number Country Code-Number-Kind Code	Date MM-YYYY	Name	Classification
*	A	US-6,492,963	12-2002	Hoch, David J.	345/39
*	B	US-6,388,871	05-2002	Masui, Takuji	361/683
*	C	US-6,328,268	12-2001	Irie, Yoshinori	248/230.1
*	D	US-5,629,668	05-1997	Downs, Robert M.	340/432
*	E	US-6,446,922	09-2002	Irie, Yoshinori	248/230.1
*	F	US-6,741,045	05-2004	Kitamura, Satoshi	318/14
*	G	US-2004/0220712	11-2004	Takeda et al.	701/035
*	H	US-2004/0172178	09-2004	Takeda et al.	701/029
*	I	US-6,418,041	07-2002	Kitamura, Satoshi	363/125
*	J	US-4,319,129	03-1982	Quintilian, Bartholomew F.	235/97
	K	US-			
	L	US-			
	M	US-			

FOREIGN PATENT DOCUMENTS

*		Document Number Country Code-Number-Kind Code	Date MM-YYYY	Country	Name	Classification
	N					
	O					
	P					
	Q					
	R					
	S					
	T					

NON-PATENT DOCUMENTS

*		Include as applicable: Author, Title Date, Publisher, Edition or Volume, Pertinent Pages)
*	U	Learoyd, Cyclometer Errors Caused by Magnet Orientation, from http://sheldonbrown.com/cyclecomputer-magnet.html , 5 pages, copyrighted 2000.
*	V	Brown, Cyclecomputer Troubleshooting, Harris cyclery, edited 11/23/2001 (from http://sheldonbrown.com/cyclecomputer-troubleshoot.html).
	W	
	X	

*A copy of this reference is not being furnished with this Office action. (See MPEP § 707.05(a).)
Dates in MM-YYYY format are publication dates. Classifications may be US or foreign.